


PT1000 adhesive sensor

Connection to bluelog Neo



PT1000 adhesive sensor: Sensor connection

Description
1 Data logger terminal, digital output / multi-input
2 PT1000 temperature sensor

Connection

Wire color	Use
● Brown	Ground
○ White	PT1000 temperature signal

Configuration data

Measurement	Input	Unit	Gradient	Offset
Temperature	PT1000	°C	1	0

Item numbers

Sensor	Item nos.
PT1000 (adhesive)	200.315