


PT1000 adhesive sensor

Connection to blue'Log XM/XC



PT1000 adhesive sensor: Sensor connection

	Description
1	Data logger terminal, digital output / multi-input
2	PT1000 temperature sensor

Connection

Wire color	Use
Brown	Ground
White	PT1000 temperature signal

Configuration data

Measurement	Input	Unit	Gradient	Offset
Temperature	PT1000	°C	1	0

Item numbers

Sensor	Item nos.
PT1000 (adhesive)	200.315