


PT1000 sensor in the housing

Connection to blue'Log XM/XC



PT1000 sensor in the housing

	Description
1	Data logger terminal, digital output / multi-input
2	PT1000 sensor in the housing

Connection

Wire	Use
(2) 4	Ground
(1) 3	PT1000 temperature signal

Configuration data

Measurement	Input	Unit	Gradient	Offset
Temperature	PT1000	°C	1	0